Mitigating the Damaging Effects of Corrosion at Port Facilities

Presented by
Brian Pailes, Ph.D., P.E., NACE CP-3
Senior Project Manager
Vector Corrosion Services

Outline

- Corrosion background
  - How and why does it happen
- Reinforced concrete structures
  - Deterioration process
  - Special considerations
- Steel structures
  - Deterioration process
- Corrosion mitigation solutions
  - Galvanic and impressed current cathodic protection

VECTOR CORROSION SERVICES

Corrosion Background

VECTOR CORROSION SERVICES

Corrosion

- Electrochemical reaction
- Requires
  - Moisture
  - Electrolyte – water or concrete
  - Metallic path – steel
- Anode
  - Where rust is formed
- Cathode
  - No section loss



Corrosion Macro-Cell



Reinforced Concrete Structures

VECTOR CORROSION SERVICES

Corrosion of Reinforced Concrete

- Concrete is naturally alkaline
  - pH of about 13
- Steel is naturally passive at this alkalinity
  - Formation of passive layer
- Passive layer can be destroyed by;
  - Chlorides
  - Carbonation

VECTOR CORROSION SERVICES

Chloride Induced

- Chloride ions diffuse into concrete and destroy steel's passive layer
- Source of chlorides
  - Marine environments
  - De-icing salts
  - Chemical/processing plants
  - Cast into concrete
- Chlorides are not consumed in corrosion reaction, therefore, once threshold concentration reached, corrosion can occur unabated

VECTOR CORROSION SERVICES

Chloride Concentration Threshold

- Generally accepted chloride thresholds
  - 350 ppm of ***concrete***
  - 0.035% by mass of ***concrete***
  - 1 .5 lbs per cubic yard of ***concrete***



VECTOR CORROSION SERVICES

Carbonation

- Carbon dioxide permeates into concrete
- Reduces pH of concrete
  - CO_2 reacts with free lime, $Ca(OH)_2$, resulting in $CaCO_3$ and H_2O
- Reduced pH de-passivates steel
- Often seen when
  - Concrete permeability is high
  - Industrial sites
  - Very old structures – carbonation is a result of time and exposure

VECTOR CORROSION SERVICES

Corrosion Induced Damage

- Damage resulting from
  - Metal section loss and
  - Formation of iron oxide (rust)
  - Expansive properties of iron oxide create tensile stresses in concrete
  - Leads to cracking, delamination, and eventual spalling



VECTOR CORROSION SERVICES

Corrosion Induced Damage

- Conventional mild reinforcing bar
  - In most cases loss of steel section not primary concern
  - Damage to concrete becomes significant and observable prior to severe section loss
- High strength steel
  - Minor section loss can have significant effect on strength
  - Can have significant section loss without significant concrete damage

VECTOR CORROSION SERVICES

Patch Accelerated Corrosion



Steel Structures

VECTOR CORROSION SERVICES

Steel Structures

- Directly exposed to environment
- Primary factors affecting corrosion
  - pH
  - Temperature
  - Moisture
    - Wetting drying cycles
  - Ion content
    - Chlorides, sulfates, etc.
  - Oxygen Content
  - Water Velocity

Source – techknowserv.com

VECTOR CORROSION SERVICES

Dissimilar Metals – Galvanic Corrosion

- Dissimilar metals in direct electrical contact with each other will result in the less noble metal corroding
  - Principal used in galvanic cathodic protection to protect a metal while sacrificing another metal.

Table 1.1 Partial Standard emf Series of Metals

Half-cell	Metal	Standard Electrode Potential E_o(volts) vs. SHE*
Au/Au^{+++}	Gold	+1.498
Pt/Pt^{++}	Platinum	+1.200
Cu/Cu^{++}	Copper	+0.345
$H_2/2H^{+}$	Hydrogen	0.000
Pb/Pb^{++}	Lead	–0.126
Ni/Ni^{++}	Nickel	–0.250
Fe/Fe^{++}	Iron	–0.440
Zn/Zn^{++}	Zinc	–0.763
Al/Al^{+++}	Aluminum	–1.662
Mg/Mg^{++}	Magnesium	–2.363

Less Noble Metal

* *Standard Hydrogen Electrode*

VECTOR CORROSION SERVICES

Stray Current Corrosion

- Currents through electrical paths other than the intended circuit
- Can cause rapid loss of steel
  - Dependent on amperage and affected surface area
- Commonly seen;
  - Electrified rails
  - Cathodicly protect utility pipes near metal structures that are not cathodicly protected

VECTOR CORROSION SERVICES

Stray Current



Corrosion Mitigation

VECTOR CORROSION SERVICES

Cathodic Protection

- Cathodic protection (CP) is a method of corrosion control through the application of direct current to a metal under protection, forcing it to become a cathode
  - Anode is where rust occur and the cathode is protected from section loss
- Two main types of CP
  - Galvanic
  - Impressed current

VECTOR CORROSION SERVICES





VECTOR CORROSION SERVICES

Impressed vs Galvanic

- Galvanic
  - Typically very low maintenance
  - Self regulating current output based on environment
    - Current output limited
  - Typically less expensive
    - Not always though
  - Limited life span – between 10 to 30 years
- Impressed
  - Provides significantly more current
    - Can reduce number of anodes
  - Long life span
    - Can be over 50 years depending on application
  - Requires maintenance

VECTOR CORROSION SERVICES

Galvanic CP

- Uses the concept of dissimilar metal corrosion in order to protect steel reinforcing.
  - Anode types;
    - Zinc
    - Aluminum
    - Magnesium
  - All are less noble than steel



VECTOR CORROSION SERVICES

Bent Cap Repairs

- Mitigate corrosion of a pier in the Dominican Republic

Steel Sheet Pile Construction



VECTOR CORROSION SERVICES


HÖEGH AUTOL

Sheet Pile Galvanic CP

VECTOR CORROSION SERVICES

Piles

- Jacketing is the most common repair strategy
  - Critical to have cathodic protection in jackets
  - FDOT discovered accelerated corrosion in jackets without CP
    - Hartt, W.H. and Rapa, M., "Condition Assessment of Jackets Upon Pilings for Florida Bridge Substructures," Final Report, WPI No. 0510803, Florida Department of Transportation, Tallahassee, Florida, April 13, 1998

VECTOR CORROSION SERVICES

Galvanic CP – Pile Jackets

- Several different types of jackets
- Dependent on the environment
  - Chloride content of water
  - Tidal range



VECTOR CORROSION SERVICES

Zinc Mesh – Tidal Jacket

- Used only in salt water environments where most of the pile length is within the tidal region
  - Requires constant exposure to salt water to keep zinc active

VECTOR CORROSION SERVICES

Above Tidal Jacket

- Commonly referred to as “wicking” jackets
- Zinc wrapped in absorbent fabric
  - Draw salt water above tidal region to keep zinc active
- Still uses a bulk anode below the water line



VCS CORROSION SERVICES

Alkali Activated Jackets

- Can be used in salt water, above tidal, brackish, freshwater, or non marine environments
  - Uses pH of mortar to activate zinc instead of salt water

VECTOR CORROSION SERVICES

Jacket Installation



Metalizing
Both Galvanic and Impressed

VECTOR CORROSION SERVICES


20E

Impressed Current



Source: Mer Lion Metals

Puerto Nuevo Terminal

- Sheet pile wall protected with impressed current CP system
  - No recent monitoring or maintenance of system

Power Source



VECTOR CORROSION SERVICES

Questions

VECTOR CORROSION SERVICES